



Site:
Hotel XXXXXX
Address:
Bucharest, Romania


Tested by:
ProLAN Solutions SRL
Bucuresti, Str. Lica Gheorghe 23
www.prolan.ro - office@prolan.ro

Written notes:

Cable ID: HOTEL BIROU 1 Written notes:

Qualified: ✓ 1000BASE-T; 100BASE-TX; 10BASE-T; Voice Over IP; 1394b S100; Telco

Date	Time	Length	Version	S/N
15.06.2011	09:04:53	84,9 m	V1.30.00	1537058



Cable ID: HOTEL BIROU 2 Written notes:

Qualified: ✓ 1000BASE-T; 100BASE-TX; 10BASE-T; Voice Over IP; 1394b S100; Telco

Date	Time	Length	Version	S/N
15.06.2011	09:14:05	85,1 m	V1.30.00	1537058



Cable ID: HOTEL BIROU 3 Written notes:

Qualified: ✓ 1000BASE-T; 100BASE-TX; 10BASE-T; Voice Over IP; 1394b S100; Telco

Date	Time	Length	Version	S/N
15.06.2011	09:16:25	84,8 m	V1.30.00	1537058



Cable ID: HOTEL BIROU 5 Written notes:

Qualified: ✓ 1000BASE-T; 100BASE-TX; 10BASE-T; Voice Over IP; 1394b S100; Telco


Date	Time	Length	Version	S/N
15.06.2011	08:42:45	92,7 m	V1.30.00	1537058



Cable ID: HOTEL BIROU 6 Written notes:

Qualified: ✓ 1000BASE-T; 100BASE-TX; 10BASE-T; Voice Over IP; 1394b S100; Telco

Date	Time	Length	Version	S/N
15.06.2011	08:43:19	92,3 m	V1.30.00	1537058



Cable ID: HOTEL BIROU 7 Written notes:

Qualified: ✓ 1000BASE-T; 100BASE-TX; 10BASE-T; Voice Over IP; 1394b S100; Telco

Date	Time	Length	Version	S/N
15.06.2011	08:45:58	92,2 m	V1.30.00	1537058



Cable ID: HOTEL BIROU 8 Written notes:

Qualified: ✓ 100BASE-TX; 10BASE-T; Voice Over IP; Telco
Disqualified: ✗ 1000BASE-T Reason: Delay Skew fault
✗ 1394b S100 Reason: Impedance fault

Date	Time	Length	Version	S/N
15.06.2011	08:34:38	93,3 m	V1.30.00	1537058

